

FIELD INSPECTION REPORT

Date of Inspection : 7/12/2020		District: Muzaffarpur
Division : Muzaffarpur East 2		Length (km):
Name of the Road: Sahibpur MMGSY Road TO Kothia		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U } N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓ No painting
4.	Compliance History Road climate due to heavy flood	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	.
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	(S)

Sd/-
12/12/20
(Signature)

NAME:

Sd/- Muzaffarpur
21.

DESIGNATION: