FIELD INSPECTION REPORT

| Date of | nspection: 9-12-2000 | District: Myzafarbur | 4 |
|------------------------------|--|--|-----------|
| Division: Muzafforbur east-2 | | Length (km): | |
| Name of | the Road: Harry Dalla Des | a to Heave eller | |
| - curing | Frogramme: MAINTENANCE | AL (O (14230L JIM | |
| Package | No.: | Road Id No.: | |
| Status o | the Project: Ongoing/Completed | /Under Maintenance | |
| Work is | n case of: New Connectivity/U | p gradation/ Maintenance | |
| Sl. No. | Parameters to | be checked | Remarks |
| 1. | Pavement | | |
| a) | Road Junction condition | S/U | |
| b) | Condition of Surfacing | | S/U |
| c) | Riding Quality | | S/U |
| d) | Road Camber | | _S/U |
| c) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | |
| ŋ | Contraction Joints provided or not (CC Pavement) | | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | | Yes/No |
| 2. | Cross Drainage | | |
| a) | Condition of head walls in Hume pi | ipe culverts including its painting | S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | | S/SRI/U N |
| c) | Condition of railings/slab/approach for Bridges | | S/SRI/U * |
| 3. | Road Furniture | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | Yes/No |
| 4. | Compliance History | | |
| a) | Status of ATR's & any others | The second secon | 1 |

Overall Rating

| Satisfactory (S) | m5 4 |
|---|------|
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

Dhy 9/14 20 (Signature)

NAME:

Bardyahath chandharro

DESIGNATION: J-E, Kunsiper -

Scanned with CamScanner