

FIELD INSPECTION REPORT


Date of Inspection : 15/12/2020	District: Muraffapur
Division : RWD WEST	Length (km): 1.627
Name of the Road: Madhukar Chapra Pokhara PMWSY sarak me Jhandi Ram ke Ghar hota hue	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 315074/2031
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Jagmala Ram
Ayodhya Sah
K ghanta

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition S	S/U
b)	Condition of Surfacing S	S/U
c)	Riding Quality S	S/U
d)	Road Camber S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. S	Yes/No
f)	Contraction Joints provided or not (CC Pavement) S	Yes/No
g)	Compaction of flank/slope & raincuts if any S	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting S	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts S	S/SRI/U
c)	Condition of railings/slab/approach for Bridges N/A	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


(Signature)

NAME: Barju Prasad

DESIGNATION: J.E.