

FIELD INSPECTION REPORT

Date of Inspection: 10.12.20		District: Arunachal Pradesh
Division: E.W.D.		Length (km):
Name of the Road: Baramulla		Package No.: MAINTENANCE
Scheme/Programme:		Work is a case of: Road Id No.: J1522912046
Status of the Project:		Ongoing/Completed/Under Maintenance
SL No.		New Connectivity/Up gradation/ Maintenance
Parameters to be checked		
1.	Pavement	Remarks
a)	Road Junction condition	
b)	Condition of Surfacing	L/S/U
c)	Riding Quality	L/S/U
d)	Road Camber	L/S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	L/S/U
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	Yes/No
a)	Condition of head walls in Hume pipe culverts including its painting	L/S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	L/S/SRI/U
c)	Condition of railings/slab/approach for Bridges	L/S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA
		N.A.

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	5
Unsatisfactory (U)	

10/12/20
(Signature) J. E. P. A. M.

NAME: Saba Narayan Pannu.

DESIGNATION: J.E.