FIELD INSPECTION REPORT

Division	1114764	17.12.2020. Harburlest	District: Mercefferder Length (km):		
	of the Road: R-	July matter	Tola Ram manthur REQ	Carday T	
STATE OF THE PARTY	Programme:	MAINTENANCE		a Haker	
Package No.: Status of the Project: O		Ongoing/Complete	Road Id No.; ngoing/Completed/Under Maintenance		
	s a case of:		Up gradation/ Maintenance		
SI. No.		Parameters to be checked		Remarks	
1.	Pavement				
a)	Road Junction condition			S \$/U	
b)	Condition of Surfacing			s S/U	
c)	Riding Quality			s S/U	
d)	Road Camber			s S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)			49es/No	
g)	Compaction of flank/slope & raincuts if any				
2.	Cross Drains	the state of the s			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			J S/SRI/L	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4.	Compliance	Compliance History			
a)	Status of ATR's & any others				

Overall Rating

10	
Satisfactory (S)	CRI
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Jiterdra kuman DESIGNATION: TE