## FIELD INSPECTION REPORT

Date of Inspection:			District:- Sitamarhi	District:- Sitamarhi.	
Division:-RWD, Works Div. Pupri. Length (km):-			Length (km):- 0 · 8	EER KAAN	
Name o	of the Road:-	Mahnagachhi	Sadikhayam to Ri	mar tule	
Scheme	e/Programme:-	MAINTEN	ANCE	001 10 -1	
	e No.:- BR33R-	-579	Road Id No.: 31607	1802085	
	of the Project:	Ongoing/Comple	eted/Under Maintenanc	e	
Work is	s a case of:		y/Up gradation/ Mainte		
Sl. No.	Parameters to be checked			Remarks	
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutments & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railing/slab/approach for bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sing board/informatory/cautionary Board/ Km & 200m stones/Pavement road marking are provided and maintained			Yes/No	
4.	Compliance I				
a)	Status of ATF	R's & any others			

Overall Rating : SRI

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: - SHIVENIZEA KR. RAVAK

(Signature) 20

DESIGNATION:- A'E