FIELD INSPECTION REPORT

	04/12/2020	District: East Chum Po	Ham
Maria San Carlos		Mengin (km): 2.44(-	4(41)
TO A COMPANY OF THE PARTY OF TH	meswaye, Jan	resug ghat via much be	or Tala
e/Programme:	MAINTENANCE	Mmasy	I le le
the second secon	Lowelland water		
THE RESERVE OF THE PARTY OF THE	New Connectivity/I	In gradetics (M. i. i.	and the same of the
A STATE OF THE PARTY OF THE PAR	2000年1月1日 1月1日 1月1日 1月1日 1月1日 1月1日 1月1日 1月1日	SN WILLIAM STATE OF THE STATE O	The second second
		Remarks	
Service Servic			, 10 x 4
Road Junction condition			S/U
Condition of Surfacing			S/U
Riding Quality			S/U
Road Camber			√S/U
Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No	
Contraction Joints provided or not (CC Pavement)		Yes/No	
Compaction of flank/slope & raincuts if any		Yes/No	
Cross Drainag	e di in		
Condition of head walls in Hume pipe culverts including its painting			8/SRI/U
Condition of Abutment & Wing walls, Slab in RCC culverts			8/SRI/U
Condition of railings/slab/approach for Bridges			S/SRI/U
Road Furnitur			3.7
Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
Compliance H	istory	计划的图像	
Status of ATR's	& any others		
	on: of the Road: e/Programme: ge No.: of the Project: s a case of: Pavement Road Junction Condition of S Riding Quality Road Camber Whether free aggregates in c Contraction Jo Compaction of A Condition of A Condition of ra Road Furnitur Whether sign stones/Pavement	of the Road: James Con & James Condition & Condition of Surfacing & Riding Quality & Road Camber & Whether free from defects such aggregates in case of CC Pavement. Contraction Joints provided or not (Compaction of flank/slope & raincu & Cross Drainage & Condition of Abutment & Wing wall Condition of railings/slab/approach & Road Furniture & Whether sign boards/informatory/or whether sign boards	of the Road: Jones Length (km): 3,445 e/Programme: MAINTENANCE Mouse ghut Maintenance Road Id No.: of the Project: Ongoing/Completed/Under Maintenance Parameters to be checked Pavement Road Junction condition Condition of Surfacing Riding Quality Road Camber Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Contraction Joints provided or not (CC Pavement) Compaction of flank/slope & raincuts if any Cross Drainage Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Compliance History

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME: A Khilah porazad

DESIGNATION: A.E Mesignation: Ase Design : JE