

FIELD INSPECTION REPORT

Date of Inspection : 06/12/2020	District: East Champaran
Division : Motihari	Length (km): 1.560
Name of the Road: NH 28 Bairiya to NH 28 Matbhawan via Babu Tola.	
Scheme/Programme: MAINTENANCE	MM 654 (SC)
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	✓
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/✓
b)	Condition of Surfacing	S/✓
c)	Riding Quality	S/✓
d)	Road Camber	S/✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N.A

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

Amol
7/12/2020
(Signature)

NAME: Anil Kumar Pd. Thakur

DESIGNATION: T.E