

FIELD INSPECTION REPORT

| Date of Inspection : | 10/12/20 | District: | East Champaran |
|------------------------|--|--------------|----------------|
| Division : | Motihari | Length (km): | 1.460 Km |
| Name of the Road: | PMUSY Road Bhargama To Harigan Tola (MMUSY) | | |
| Scheme/Programme: | MAINTENANCE MMUSY(SC) | | |
| Package No.: | — | | |
| Road Id No.: | — | | |
| Status of the Project: | Ongoing/Completed/Under Maintenance ✓ | | |
| Work is a case of: | New Connectivity/Up gradation/ Maintenance | | |
| Sl. No. | Parameters to be checked | Remarks | |
| 1. | Pavement | | |
| a) | Road Junction condition | ✓S/U | |
| b) | Condition of Surfacing | ✓S/U | |
| c) | Riding Quality | ✓S/U | |
| d) | Road Camber | ✓S/U | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | ✓Yes/No | |
| f) | Contraction Joints provided or not (CC Pavement) | ✓Yes/No | |
| g) | Compaction of flank/slope & raincuts if any | ✓Yes/No | |
| 2. | Cross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | ✓S/SRI/U | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | ✓S/SRI/U | |
| c) | Condition of railings/slab/approach for Bridges | ✓S/SRI/U | |
| 3. | Road Furniture | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓Yes/No | |
| 4. | Compliance History | NA | |
| a) | Status of ATR's & any others | . | |

Overall Rating :

| | |
|---|---|
| Satisfactory (S) | S |
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

NAME: Rajendra Prasad Yadav

DESIGNATION: A.E

(Signature)  10/12/20