

FIELD INSPECTION REPORT

Date of Inspection:	2026 7/12/20	District:	East Champaran
Division:	Mohibpur	Length (km):	0.850
Name of the Road:	Nussuddin Annwar's ghore. Koushthi prasad's ghore		
Scheme/Programme:	MAINTENANCE	GTNSY	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N-A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Finding: 150.0m Road surface damage due to flood 2020. Rest surface Satisfactory. 1st damaged strip not interested in FDR M.S. permanent restoration required.

NAME: Akhilesh
DESIGNATION: A.E

Name: Ajay Kumar
Design: J.E

08/12/2020