

FIELD INSPECTION REPORT

Date of Inspection : 04/12/2020		District: East Champaran
Division : Motihuari		Length (km): 0.750
Name of the Road: G.P.S. Chitaha & P.M.C.S. Road Chitaha T.K.		
Scheme/Programme: MAINTENANCE		G.T.N.S.Y
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	N.A

N.A
Damaged
due to flood
2020.

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Finishing : 70.0m Road surface & one No. 1000mm dia culvert damaged due to flood 2020. Rest Road surface satisfactory. Flood damage report entered in FDR MIS. Motorable work is done but permanent restoration is required.

(Signature)

NAME: Akhilesh Prasad
DESIGNATION: A.E

Name: AJAY KUMAR
DESIGN: J.E

05/12/2020
J.E

05/12/2020
A.E.