

FIELD INSPECTION REPORT

Date of Inspection : 17/12/20		District : East Champaran
Division : Chakia		Length (Km):
Name of the Road : SH74 bndhiya mai sthan to Sundrapur.		
Scheme/Programme :		MAINTENANCE
Package No.:		Road ID No.:
Status of the Project :		Ongoing/Completed/Under Maintenance
Work is a case of :		New Connectivity/Up Gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	U
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes
f)	Contraction Joints provided or not (CC Pavement)	NA
g)	Compaction of flank/slope & raincuts if any	NO
2,	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	Yes
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	NA
c)	Condition of railings/slab/approach for Bridges	NA
3,	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	N/O
4,	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :	Satisfactory (S)	-
	Satisfactory but requires improvement (SRI)	SRI
	Unsatisfactory (U)	-

Road damage due to flood 2020.

[Signature]
17/12/20
(Signature)

NAME :
DESIGNATION :