FIELD INSPECTION REPORT

Date of la	aspection :	6-12-2020	District: NALANDA	
DI 11 110 0 -10 1-			Length (km): 0.500	
Name of	the Road: Ka	you bigton pe	ob At to chourt you	
		MAINTENANCE		
Package	No.:		Road Id No.:	
Status of	the Project:	Onguing/Complete	ed/Under Maintenance	
Work is a case of: New Connectivity		New Connectivity	/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked			Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/UV
c)	Riding Quality			S/U ✓
d)	Road Camber			· S/U~
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
n	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compection of flank/slope & raincuts if any			Yes/No
2.,	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
\$21.5°	Compliance History			
a)	Status of ATR's & any others			P. Carlon

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(Signature)

muly

NAME: murel 12 Six.

DESIGNATION: A'E

Scanned with CamScanner