

FIELD INSPECTION REPORT

Date of Inspection : 17.12.2020	District: West Champaran
Division : Narkatinganj	Length (km):
Name of the Road: Chukazi to Khairwa Tola	
Scheme/Programme: MAINTENANCE ✓	
Package No.: BR77R 372	Road Id No.: 31808902208
Status of the Project: Ongoing/Completed/Under Maintenance ✓	
Work is a case of: New Connectivity/Up gradation/ Maintenance ✓	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	yes
f)	Contraction Joints provided or not (CC Pavement)	yes
g)	Compaction of Bank/slope & raincuts if any	NO
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA
c)	Condition of railings/slab/approach for Bridges	NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	yes
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—


17/12/2020
(Signature)

NAME: JAY PRAKASH RAM

DESIGNATION: JE