


FIELD INSPECTION REPORT

Date of Inspection : 16-12-2020		District: W. Champaran	
Division : Nalhatiyanj		Length (km): 6.28 km	
Name of the Road: Dhobha L022 to Tindawa			
Scheme/Programme: MAINTENANCE			
Package No.: BR-37R-458		Road Id No.: 31808902215	
Status of the Project: Ongoing/Completed/Under Maintenance		Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	SRI
c)	Riding Quality	SRI
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
f)	Contraction Joints provided or not (CC Pavement)	—
g)	Compaction of flank/slope & raincuts if any	SRI
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—


 16/12/2020
 (Signature)

NAME: BIPIN KUMAR

DESIGNATION: J.E.