

FIELD INSPECTION REPORT

Date of Inspection : 16.12.2020		District: West Champaran
Division : Madhubani		Length (km):
Name of the Road: 604 to Siachhap		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance ✓		
Work is a case of: New Connectivity/Up gradation/ Maintenance ✓		
Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	2
b)	Condition of Surfacing	2
c)	Riding Quality	2
d)	Road Camber	3
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	yes
f)	Contraction Joints provided or not (CC Pavement)	yes
g)	Compaction of flank/slope & raincuts if any	NO
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	2
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA
c)	Condition of railings/slab/approach for Bridges	NA
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	yes
4. Compliance History		
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	1
Unsatisfactory (U)	1

NAME: JAY PRAKASH RAM

DESIGNATION: J-E

(Signature)
16/12/2020