

FIELD INSPECTION REPORT

Date of Inspection:	16/12/20	District:	Barbhangha
Division:	Barbhangha-I	Length(Km):	1.020
Name of Road:	L054-L023 to Fakirana		
Scheme/Programme:	Maintenance (PMGSY)		
Package No.	BR-10R-126	Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
S No.	Parameters to be Checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U S	
b)	Condition of Surfacing	S/U S	
c)	Riding Quality	S/U S	
d)	Road Camber	S/U S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No NA Y	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA Y	
g)	Compaction of flank /slope & raincuts if any	Yes/No N	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N A	
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts	S/SRI/U N A	
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U N A	
3	Road Furniture		
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No Y	
3	Compliance History		
a)	Status of ATR's & any others	N	
Overall Rating:			
Satisfactory (S)			
Satisfactory but requires Improvement (SRI)		SRI	
Unsatisfactory (U)			

Some Part of damage due to flood 2020

Name:

Designation:

(Signature)

[Signature]
16/12/20