

FIELD INSPECTION REPORT

Date of Inspection: 17-12-20	District: Nalanda
Division: Patna Hilsa	Length (km): 1.755 Km
Name of the Road: 705 Rasulpur to Blomethy	
Scheme/Programme: MAINTENANCE	Mainten
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	Under Mainten
Work is a case of: New Connectivity/Up gradation/ Maintenance	Mainten

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	U S
b)	Condition of Surfacing	U S
c)	Riding Quality	U S
d)	Road Camber	U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Y No S
f)	Contraction Joints provided or not (CC Pavement)	Y No S
g)	Compaction of flank/slope & raincuts if any	Y No S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRIU S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRIU S
c)	Condition of railings/slab/approach for Bridges	S SRIU S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Y No Yes
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

Pradeep Kumar Arora

(Signature)
17/12/20
20