

FIELD INSPECTION REPORT

Date of Inspection : 8-12-2020	District: DARBHANGA
Division : Benipur	Length (km): 2.33KM
Name of the Road: - UJAN TO AWAM.	
Scheme/Programme: MAINTENANCE	
Package No.: BROR 238	Road Id No.:
Status of the Project: Ongoing Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl.No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/U
b)	Condition of Surfacing	✓/U
c)	Riding Quality	✓/U
d)	Road Camber	✓/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓/No
f)	Contraction Joints provided or not (CC Pavement)	✓/No
g)	Compaction of flank slope & raincuts if any	✓/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓/SRI/U
c)	Condition of railings/slab approach for Bridges	✓/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓/No
4.	Compliance History	
a)	Status of ATR's & any others	ATR

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

8/12/2020
J-E

8/12/2020
AE

NAME: PRADEEP KUMAR

(Signature)

DESIGNATION: J-E