

FIELD INSPECTION REPORT

PMUSY

Date of Inspection :	7-12-2020	District:	DG86Langa
Division :	Beli P4R	Length (km):	2.394 km.
Name of the Road:	L033-T02 to B4rheb 9nayot P4R.		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR 10 R17	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	-S/U
b)	Condition of Surfacing	-S/U
c)	Riding Quality	-S/U
d)	Road Camber	-S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-S/SRI/U
c)	Condition of railings/slab/approach for Bridges	-S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

7-12-2020
Mol-safique

DESIGNATION: J.E.

7-12-2020 (Signature)
Ab