

FIELD INSPECTION REPORT

Date of Inspection : 16.12.2020		District: Darbhanga.	
Division : BENIPUR		Length (km): - 2.30 Km	
Name of the Road: - L034 To2 TO Nadiyami			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance ✓	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/S/U
b)	Condition of Surfacing	✓/S/U
c)	Riding Quality	✓/S/U
d)	Road Camber	✓/S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓/Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓/Yes/No
g)	Compaction of flank/slope & raincuts if any	✓/Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓/S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓/S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓/S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓/Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Prajeep
16/12/2020

Shashi
16/12/2020
AE

(Signature)

NAME: PRAJEEP KUMAR

DESIGNATION: JE