FIELD INSPECTION REPORT

GTSMY		Day I Lava
Date of Inspection:	7-12-2020	District: Darbhange
The state of the s	Mi PHY	Length (km): 1.522 km.
Name of the Road:	To3 to you	dar Toli
Scheme/Programme:	MAINTENANCE	
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/U	Jp gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks	
1.	Payement		
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	∽S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	~8/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SR.I-
Unsatisfactory (U)	

NAME: Md: 59 finer
DESIGNATION: YE