FIELD INSPECTION REPORT

Date of Inspection: 17/12/20			District: Madhubani	
Division: Thoughas Put			Length (km): 1.627 kur	
Name o	f the Road:	Sohpur to fai	sa Mahadalit tol.	
Scheme	Programme:	MAINTENANCE	MMGSY	
			Road Id No.: I/Under Maintenance	
SI. No.	对	Parameters to b	e checked	Remarks
	Pavement	EKengalia vilaggile	Significant March 1945	
a)	Road Junction condition			LS/U
b)	Condition of Surfacing			_S/U
(ç)	Riding Quality			S/U_
d)	Road Camber S/L			S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
1.2.	Cross Drainag	Ciation The same		
a)	Condition of head walls in Hume pipe culverts including its painting			s/sri/u
h)	Condition of Abutment & Wing walls. Slab in RCC culverts			K/RRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign	boards/informatory/cau	tionary Board/km & 200m	Yes/No

stones/Pavement road markings are provided and maintained

Overall Rating

a)

47

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	"SRI
Unsatisfactory (U)	

(Signature) (Signature)

Yes/No

NAME: SUJEET KUMAR J.E.

Compliance History

Status of ATR's any others ----