FIELD INSPECTION REPORT

Division: Than Than Division: Length (km): 1.270			rict: Madhuban gth (km): 1.270 Ko		
	7147		s PMNsy Roed Pasto		
Scheme	Programme:	MAINTENANCE		7,137	
Package No.:			Road Id No.:		
	f the Project:	Ongoing/Completed/Unde		r Magnt	
Work is	a case of:	New Connectivity/Up grad	lation/ Maintenance		
Sl. No.		Parameters to be che	ecked	Remarks	
1.	Pavement				
a)	Road Junction	condition	S/U S		
b)	Condition of Surfacing			S/U _S	
c)	Riding Quality			S/U g	
d)	Road Camber			S/U_S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)		Yes/No		
g)	Compaction of flank/slope & raincuts if any		Yes/No N		
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U SP		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U		
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No N	
4.	Compliance H	istory	97448 1974 17 17 17 17 17 17 17		
	a	s & any others			

Satisfactory (S)		
Satisfactory but requires Improvement (SRI)	SRJ	
Unsatisfactory (U)		

(Signature)

NAME: Dhananjay kyonandesignation: J.E