## FIELD INSPECTION REPORT

Date of I	nspection:	7/12/20	District: Madhubacc	
Division: Thanjharfur			Length (km): 0.937	
Name of	the Road:		good to Dhanuk TOL	
Scheme/l	Programme:	MAINTENANCE	MMGSY Roud Id No.:	
Package	No.:			
	the Project:		/Under Maintenance	
			y/Up gradation/ Maintenance	
SI. No.		Parameters to	be checked	Remarks
1.1	Pavement		de la Carte de La Carte de La Carte de La La Carte de La Carte de	John in the
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
(2	Riding Quality			S/U
d)	Road Camber			SAU
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Candition of Abutment & Wing walls, Slab in RCC culverts			KIRRIALI
c)	Condition of railings/slab/approach for Bridges			S/SRI/U pr
3.	Road Furniture			
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained  Yes/No			
42	Compliance History			
(н)	Status of ATR	any others	•	N/A

Overall Rating

Satisfactory (S)	/
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	"U"

(Signature) (Signature)

NAME: SUJEET KUMAR J.E.