

FIELD INSPECTION REPORT

Date of Inspection : - 17.12.2020	District: - Nalanda
Division : - Hilsa	Length (km): - 0.760 km
Name of the Road: - Hilsa chiksaurs RBO Road chandant Pul To Dakehe's	
Scheme/Programme: MAINTENANCE (MMGSY)	Ganipur V's Samud Bhaun
Package No.:	Road Id No.:
Status of the Project: Ongoing Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SN
b)	Condition of Surfacing	SN
c)	Riding Quality	SN
d)	Road Camber	SN
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SN/Nil
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SSRI
c)	Condition of railings/slab/approach for Bridges	SSRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained 200m post not found.	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Samsung Quad Camera
Shot with my Galaxy A51

17/12/20
(Signature) AE

Anesh Kumar Mandal