

Today, 19:58

INSPECTION REPORT

Date of Inspection : 17/12/2020		District: Nalanda	
Division : Hi/8a		Length (km): 0.095 km	
Name of the Road: Barimath Pilich road to Barimath			
Scheme/Programme: MAINTENANCE		GTSNY	
Package No.:		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		Completed under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓	
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SR/U	NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓ Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	No ATR	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

Signature
17/12/2020
(Signature)

NAME: Gaurish Kumar Singh
JE/Panaji