

FIELD INSPECTION REPORT

Date of Inspection :	16.12.20	District:	Maya
Division :	IMAMGANS	Length (km):	
Name of the Road:	T03 to Pokhara		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR12R-523	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U - S
b)	Condition of Surfacing	S/U - S
c)	Riding Quality	S/U - S
d)	Road Camber	S/U -
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No -
f)	Contraction Joints provided or not (CC Pavement)	Yes/No -
g)	Compaction of flank/slope & raincuts if any	Yes/No - rain cuts & shoulders found
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI -
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI -
c)	Condition of railings/slab/approach for Bridges	S/SRI/U - N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	Yes/No -
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(SRI)

[Signature]
(Signature)

NAME: