


# FIELD INSPECTION REPORT

Date of Inspection : 16/12/2020		District : GAYA	
Division : Neemchak Bathani		Length (Km. : 0.757 KM.	
Scheme/Programme:		MAINTENANCE PMGSY (L082 - Jethiyan Ghati Jamua Rd To Dharam Bigha	
Package No. :		BR-12R-733	Road Id No. :
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked		Remarks
1	Pavement		S S/U
a)	Road Junction condition		S S/U
b)	Condition of Surfacing		S S/U
c)	Riding Quality		S S/U
d)	Road Camber		Yes Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes Yes/No
g)	Compaction of flank/slope & raincuts if any		
2	Cross Drainage		S S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting		NA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges		
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes Yes/No
4	Compliance History		
a)	Status of ATR's & any others.		NO ATR

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Vijay Kumar Pandey  
Assistant Engineer

  
16/12/2020  
AE