FIELD INSPECTION REPORT

_			THE CALL
D	Date of Inspection: 15.12.	District: JEHANABAD	
D	Division: Tchangha	Length (km): A A	
Name of the Road: 1076 Babhang Shakurabad Mill to Beldari Bibka.			
So	cheme/Programme: PMC	MAINTENANCE	
Pa	ackage No: BR14R343	Road Id No.:	
St	Status of the Project: Ongoing/Completed/Under grad		
W	ork is a case of:	New Connectivity/Up gradation/Maintenance	
S	V Paramet	ers to be cheeked	Remarks
	Payment -		A COMMINS
a) Road Junction condition		Ts/U
b) Condition of Surfacing		S/U
C) Riding Quality		S/U
ď) Road Camber		S/U
e)	Whether free from defect	s such as visible cracks, exposed	
	aggregates in case of CC		
f)			Yes/No
g)			Yes/No
2	Cross Dramage		
a)	Condition of head walls	in Hume pipe culverts including	S/SRI/U
	its painting		1. 6. A.C.
b)	Condition of Abutment	& Wing walls, Slab in RCC	S/SRI/U
	culverts.		
c)	Condition of railings/slab/	approach for Bridges	S/SRI/U —
	Road Furniture		
a)	Whether sign boards/infor	matory/cautionary Board/km &	Yes/No Not
	200m stones/Pavement ro	ad markings are provided and	resino i
	maintained		
	Compliance History		
a)	Status of ATR's & any other	ers	NA
-			-

Overall Rating:

Satisfactory (S)		
Satisfactory but requires	501	
Improvement (SRI)	7	
Unsatisfactory (U)	_	

NAME: Blad Kympa DESIGNATION: AS