


## FIELD INSPECTION REPORT

Date of Inspection: 17.12.20		District: JEHANABAD	
Division: R.W.D. Jehanabad.		Length (km): 1.303 Km	
Name of the Road: Barawan Road to Parkothia			
Scheme/Programme:		MAINTENANCE	
Package No: BR14R399		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under gradation/Maintenance	
Work is a case of:		New Connectivity/Up gradation/Maintenance	
S.N.	Parameters to be checked	Remarks	
<b>1. Pavement</b>			
a)	Road Junction condition	S/U	S
b)	Condition of Surfacing	S/U	S
c)	Riding Quality	S/U	NA
d)	Road Camber	S/U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	yes
f)	Contraction joints provided or not (CC Pavement)	Yes/No	No
g)	Compaction of flank/slope & raincuts if any	Yes/No	yes
<b>2. Gross Drainage</b>			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
<b>3. Road Furniture</b>			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	yes
<b>4. Compliance History</b>			
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	X

  
 17/12/20  
 Signature

NAME: Arjun Chaudhary  
 DESIGNATION: JE