

FIELD INSPECTION REPORT

Date of Inspection:	18/12/2020	District: JHARKHAND
Division:	Jharkhand	Length (km): 2.955
Name of the Road:	To, to Tagadi	
Scheme/Programme:		MAINTENANCE
Package No:		Road Id No:
Status of the Project:	Ongoing/Completed/Under gradation/Maintenance	
Work is a case of:	New Connectivity/Up gradation/Maintenance	

S.N	Parameters to be checked	Remarks
1.	Payment	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

Deep
18/12/2020

NAME: - UMESH KUMAR
DESIGNATION: A.E/modangar