

FIELD INSPECTION REPORT

Date of Inspection :	17/12/2020	District:	Nalanda
Division :	H/15a	Length (km):	1.015 km
Name of the Road:	PMGSY Alawan Road to West Kirtipur		
Scheme/Programme:	MAINTENANCE - PMGSY PKH/942/295 (VR-13)		
Package No.:	Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance	Completed under maint	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	New Connectivity	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SR/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SR/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

"S"

(Signature)

NAME: Ganesh Kumar Rayan
JB/Parwalpur