FIELD INSPECTION REPORT

Date of Inspection : /	6/12/2020	District: Kaimu	1
Division: Mohania		Length (km): 1.800	um
Name of the Road: Lo	77-L024 TO	Durgapus	
Scheme/Programme:	MAINTENANCE		PMUSY
Package No.: BROSSSO		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/U	Jp gradation/ Maintenance	

Sl. No.	Parameters to be checked	Yg.	Remarks
1.	Pavement	1.9	
a)	Road Junction condition		VS/U
b)	Condition of Surfacing		√\$/U
c)	Riding Quality	Marie Control Association	√ŝ/U
d)	Road Camber		√s/u
e)	Whether free from defects such as visible cracks, exaggregates in case of CC Pavement.	posed	√Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Aes/No
g)	Compaction of flank/slope & raincuts if any		Ves/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its pa	ainting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
e)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture	David San	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m	Yes/No
4.	Compliance History		
a)	Status of ATR's & any others	Van Bronder to	

Mot warefaired

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SIRI
Unsatisfactory (U)	>1/+

betweet painting and R.F not maintained Rocal Flance Also not maintained.

16/12/20

NAME: Md. Jamil Abul Hassay