

FIELD INSPECTION REPORT

Date Of Inspection		16/12/2020	District	Bhojpur
Division		Pi20	Length (km):	2.85
Name of the Road:		A.W.D Road to Bihampur Lo23		
Scheme/Programme		MAINTENANCE		
Package No.:		Road Id No.: 10401802090		
Status of the Project :		Ongoing/Completed/Under Maintenance		
Work is a case of :		New Connectivity/Up gradation/Maintenance		
SI No.	Parameters to be checked		Remarks	
1	Pavement			
a)	Road Junction condition		S/U	
b)	Condition of Surfacing		S/U	
c)	Riding Quality		S/U	
d)	Road Camber		S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No	
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of flank/slope & raincuts if any		Yes/No	
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U NA	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U NA	
3	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No but not maintained	
4	Compliance History			
a)	Status of ATR's & any others			

Overall Rating :

Satisfactory (S)	
Satisfactory but requires improvement (SRI)	N SRI
Unsatisfactory (U)	

Name:

Ashok Kumar

Designation

SE

(Signature)

16/12/2020