Date of l	Inspection G	6.12-2020 aya	District: Gayle: Length (km): 1,066 Kross: Length (km): Gagatznakpur	
Name of	the Road: Lo	MAINTENANCE	Prigsy	
Package No.: BR-12R Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance		
SI. No.	manager of the same	Parameters.	to be checked	
1.	Pavement			₩S/U
a)	Road Junction condition			SAUL
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			
e)	Whether free from defects such as visible day, years aggregates in case of CC Pavement.			Yes/No Yes/No
f)	Contraction Joints provided or not (CC Pavement)			and the state of t
g)	Compaction of flank/slope & raincuts if any			Yes/No
2				
	Condition of head walls in Hume pipe culverts including its painting			V S/SRI/U
a)	Condition of Abutment & Wing walls, Slab in RCC culverts S/SRL			S/SRI/U
b)	Condition of railings/slab/approach for Bridges			S/SRI/U
c)	是一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个			The Res
a)	Whether sign boards/informatory/cautionary Board/km & 200m Yes/N stones/Pavement road markings are provided and maintained			Yes/No
1	Compliance Europy The Compliance Company			17
8)	Chatris of A	TR's & any others	in the state of th	MO

Overall Rating

一个,我们就是这样,他	
Satisfactory (S)	
Satisfactory but requires Im	Provement (SPD)
Unsatisfactory (U)	U.
The second secon	and any the Comment of the Comment o

NAME: Granchyam Pathok Buky:
DESIGNATION: E.F.