

FIELD INSPECTION REPORT

Date of Inspection : 16.12.2020	District: Gaya
Division :	Length (km): 1.018 km
Name of the Road: L046 Habibpur Chakrand Tekari to Niyazi	
Scheme/Programme: MAINTENANCE	PMGSY.
Package No.: BR-12R-951	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: ☒ New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A.
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

NAME:

DESIGNATION:

(Signature)

Executive Engineer