

FIELD INSPECTION REPORT

Date of Inspection :	17.12.2020	District :	Bhagalpur
Division :	Nawgachhiya	Length (km) :	1.497 km
Name of the Road :	L041 - NH 31 to Sadhua Chapar village (VR 24)		
Scheme/Programme :	Maintenance PMWSY I		
Package No. :	BR 06R 337	Road Id No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance	PMWSY I	
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameteres to be checked	Remarks	
1	Pavement	S/U	
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Road Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage	S/SRI/U	
a)	Condition of head walls in Hume pipe culvert including its painting.	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Cross Drainage	Yes/No	
a)	Whether sign boards/informatory/cautionary Boards/ km & 200m stones/Pavements roads marking are provided and maintained.	Yes/No	
4	Compliance History	No ATR	
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Road remains affected by flood. Motoration work done. Full restoration estimate (Part B) is being prepared.

(Signature)

NAME :

DESIGNATION :

1. Ramesh Chandra Prasad

Ex. Ex. RWD (WD) Nawgachhiya

2. Himanshu Shankar Prasad

A.E., Rongra Chowra

R.P. 18/12/20
कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग
कार्य प्रमण्डल नवगछिया
17.12.2020
AE