

10/12/2020

FIELD INSPECTION REPORT

Date of Inspection	17/12/2020	District	Bhagalpur
Division	Katihar	Length (km)	1.250 Km
Name of the Road	Old Jola to PMGSY Road (Sambhar Jola)		
Section/Programme	MAINTENANCE	GTSNY	
Package No.		Road Id No.	
State of the Project	Ongoing/Completed/Under Maintenance	Under Maintenance	
Work is a part of	New Connectivity/Up gradation/ Maintenance		
1. Pavement			
a)	Road Junction Condition	S/U	S
b)	Condition of Surfacing	S/U	S
c)	Riding Quality	S/U	S
d)	Road Camber	S/U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	Yes
f)	Construction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of Bank/slope & raincuts if any	Yes/No	NA
2. Culverts/Bridges			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Yes
4. General Remarks/History			
a)	State of A/R & any others		NO

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Signature
17/12/2020

NAME