

"BANMANKHI"


FIELD INSPECTION REPORT

Date of Inspection : 17/12/20	District: PURNEA
Division : R.W.D. Purnea	Length (km): 3.030 Km
Name of the Road: L87- Bahora Fatak to Musuria	
Scheme/Programme: MAINTENANCE	PM 657 2016-17
Package No.: BR-27R-413	Road Id No.: —
Status of the Project: Ongoing/Completed/Under Maintenance	✓
Work is a case of: New Connectivity/Up gradation/ Maintenance	✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—


 17/12/20
 (Signature)

NAME: PANCHANAN MOOSHI
 DESIGNATION: A.E., Bahmankhi