

# BANMANKHI

## FIELD INSPECTION REPORT

|                                                               |                           |
|---------------------------------------------------------------|---------------------------|
| Date of Inspection : 17/12/20                                 | District: PURNEA          |
| Division : R.W.D. Purnea                                      | Length (km): 1.710 Km     |
| Name of the Road: Pakka Rd. to Harbhanga                      |                           |
| Scheme/Programme: MAINTENANCE                                 | ✓ M.M.G. 27 (Gen) 2015-16 |
| Package No.: —                                                | Road Id No.: —            |
| Status of the Project: Ongoing/Completed/Under Maintenance    | ✓                         |
| Work is a case of: New Connectivity/Up gradation/ Maintenance | ✓                         |

  

| Sl. No. | Parameters to be checked                                                                                             | Remarks |
|---------|----------------------------------------------------------------------------------------------------------------------|---------|
| 1.      | Pavement                                                                                                             | ✓       |
| a)      | Road Junction condition                                                                                              | S/U     |
| b)      | Condition of Surfacing                                                                                               | S/U     |
| c)      | Riding Quality                                                                                                       | S/U     |
| d)      | Road Camber                                                                                                          | S/U     |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No  |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No  |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No  |
| 2.      | Cross Drainage                                                                                                       |         |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U |
| 3.      | Road Furniture                                                                                                       |         |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No  |
| 4.      | Compliance History                                                                                                   | —       |
| a)      | Status of ATR's & any others                                                                                         | No.     |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) | — |
| Unsatisfactory (U)                          | — |

NAME: PANCHANAN MUNSHI  
DESIGNATION: A.E, Banmankhi

(Signature)