FIELD INSPECTION REPORT

Date of	Inspection:- \	6-12-20 1	District:- Sheohar.	
Division	n:-RWD, Work	s Div. Sheohar	Length (km):- \ 시	D Q. YOKM
Name o	of the Road:- \	62 to Sahbait	TENGRAPHE SAME	iola
Scheme	Programme:-	MAINTENANO	CE PMGSY	
Packag	e No .: - BRBZA		Road Id No.:	-
Status	of the Project:	Ongoing/Completed/		
	s a case of:	New Connectivity/Uj		
SI. No.		Parameters to be chee	eked	Remarks
1.	Pavement			-
a)	Road Junction condition			\S/U
b)	Condition of Surfacing			S/U/
c)	Riding Quality		√S/U	
d)	Road Camber	Road Camber		YS/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No	
2.	Cross Draina			
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U	
b)	Condition of Abutments & Wing walls, Slab in RCC culverts		~S/SRI/U	
c)	Condition of r	ition of railing/slab/approach for bridges		S/SRI/U
3.	Road Furniture			
a)		board/informatory/c stones/Pavement ro maintained		Ves/No
4.	Compliance H			
a)		's & any others		NO

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	SRI

Name: Dilip Kunder

DESIGNATION: Judios Engineer

(Signature) 16-12-20