

FIELD INSPECTION REPORT


Date of Inspection : 03/12/2020		District: EAST CHAMPARAN
Division : MOTIHARI		Length (km): 2.366 KM
Name of the Road: L076 SINGHIYA HIBAN TO AJAGARI		
Scheme/Programme: MAINTENANCE		PM 654
Package No.: BR-112-659		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

150 M. surface length damaged due to flood 2020.



 (Signature) 31/12/20 AE

NAME: AKHILESH PRASAD

DESIGNATION: A.E, WORKS SUB-DIVISION, BANJARIYA
(MOTIHARI DIVISION)

NAME: ABHIMANYU TANTI

DESIGNATION: J.E, BANJARIYA/KOTWA


 03/12/20 J.E