## FIELD INSPECTION REPORT

Date of	Inspection:	18/12/20	District: Purri chambria	~	
Division: mon Kala			Length (km): 1,734	Length (km): 1.734	
		and the second s	alk rola,		
	Programme:	MAINTENAN			
Package No.: BR-11R - 695				Road Id No.:	
	of the Project:		pleted/Under Maintenance		
	a case of:	- 1.08-4 SX	ivity/Up gradation/ Maintenance	CHT SPECIAL CA	
Sl. No.	Parameters to be checked			Remarks	
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/N	
c)	Riding Quality			√8/Ú	
d)	Road Camber			<b>√</b> 8/U	
c)	Whether free aggregates in c	Yes/Nø			
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			¥és/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			&/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			√S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4.	Compliance History				
a)	Status of ATR's & any others			AIM	

Overall Rating

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	_
Unsatisfactory (U)	'υ',

(Signature)

NAME.

MORESHWAY SHARMAN

DESIGNATION:

J.E.