

FIELD INSPECTION REPORT

Date of Inspection :	16-12-2020	District:	W. Champaran
Division :	Nalkeatiganj	Length (km):	2.00 km
Name of the Road:	LD76-6073 to Amun +019		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-37R-610	Road Id No.:	31808902244
Status of the Project:	Ongoing/Completed/Under Maintenance		Under maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
f)	Contraction Joints provided or not (CC Pavement)	—
g)	Compaction of flank/slope & raincuts if any	S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

BKumar
16/12/2020
(Signature)

NAME: B PIN KUMAR

DESIGNATION: J.E.