

FIELD INSPECTION REPORT

Date of Inspection : 17-12-2020		District: West Champaran
Division : Nalhatiaganj		Length (km): 2.5 km
Name of the Road: L023 to Nihat Shekhuniya to Murla		
Scheme/Programme: MAINTENANCE		
Package No.: BR-37R-613		Road Id No.: 31808902247
Status of the Project: Ongoing/Completed/Under Maintenance		Under Maintenance
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	SRI
c)	Riding Quality	SRI
d)	Road Camber	SRI
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes
g)	Compaction of flank/slope & raincuts if any	—
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	SRI
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

B. Kumar
17/12/2020
(Signature)

NAME: BIPIN KUMAR

DESIGNATION: J.E.