FIELD INSPECTION REPORT

475NY

Date of Inspection:	6.12.7020	District: DARBIAHOR
Division: BE	NPUR	Length (km): - 1.20 Km
Name of the Road:	702 70 M45	Kerj- Toli
Scheme/Programme:	MAINTENANCE	1 .
Package No.: UT	ISNY.	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
Ŋ	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	10 Pag.
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	(5)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

16/12/2012 AG

(Signature)

NAME: PRADEEP KUMAR

DESIGNATION: J.E

NA