

# FIELD INSPECTION REPORT

PTSNY

| Date of Inspection : 17.12.2020                              |                                                                                                                      | District: Begusari                         |
|--------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|--------------------------------------------|
| Division : Balia                                             |                                                                                                                      | Length (km): 0.300                         |
| Name of the Road: Sandbag House of Gutukal to Hossain, Balia |                                                                                                                      |                                            |
| Scheme/Programme: MAINTENANCE                                |                                                                                                                      |                                            |
| Package No.:                                                 |                                                                                                                      | Road Id No.: 32016618602                   |
| Status of the Project:                                       |                                                                                                                      | Ongoing/Completed/Under Maintenance        |
| Work is a case of:                                           |                                                                                                                      | New Connectivity/Up gradation/ Maintenance |
| Sl. No.                                                      | Parameters to be checked                                                                                             | Remarks                                    |
| 1.                                                           | Pavement                                                                                                             |                                            |
| a)                                                           | Road Junction condition                                                                                              | ✓S/U                                       |
| b)                                                           | Condition of Surfacing                                                                                               | ✓S/U                                       |
| c)                                                           | Riding Quality                                                                                                       | ✓S/U                                       |
| d)                                                           | Road Camber                                                                                                          | ✓S/U                                       |
| e)                                                           | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No ✓                                   |
| f)                                                           | Contraction Joints provided or not (CC Pavement)                                                                     | ✓Yes/No                                    |
| g)                                                           | Compaction of flank/slope & raincuts if any                                                                          | Yes/No                                     |
| 2.                                                           | Cross Drainage                                                                                                       |                                            |
| a)                                                           | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓S/SRI/U                                   |
| b)                                                           | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U NA                                 |
| c)                                                           | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U NA                                 |
| 3.                                                           | Road Furniture                                                                                                       |                                            |
| a)                                                           | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No ✓                                   |
| 4.                                                           | Compliance History                                                                                                   |                                            |
| a)                                                           | Status of ATR's & any others                                                                                         |                                            |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            |     |
| Satisfactory but requires Improvement (SRI) |     |
| Unsatisfactory (U)                          | "U" |

NAME: Rameshwar Choudhary  
DESIGNATION: Executive Engineer

(Signature)  
Executive Engineer  
RWD Works Division, Balia