

FIELD INSPECTION REPORT

Date of Inspection :	16.12.2020	District:	Punjab
Division :	Balsi	Length (km):	1.170 KM
Name of the Road:	Phulwari to Runki		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U 'S'
b)	Condition of Surfacing	S/U 'S'
c)	Riding Quality	S/U 'S'
d)	Road Camber	S/U 'S'
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes NA
g)	Compaction of flank slope & raincuts if any	Yes/No Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U 'S'
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/ NA
c)	Condition of railings/slab approach for Bridges	S/SRI/ NA
3.	Road Furniture	
a)	Whether sign boards, informatory, cautionary Board 1 km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

"S"

NAME:

Asim Kumar

16/12/2020
(Signature) A. E. Balra