

FIELD INSPECTION REPORT

Date of Inspection :	16.12.2020	District:	Punhea
Division :	Balsi	Length (km):	1.0 km
Name of the Road:	Pankiasahi to Chunamasi		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance ☒		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ☒		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank slope & raincuts if any	Yes/No Yes
2.	Cross-Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U "S"
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U "S"
c)	Condition of railings/slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

"S"

NAME:

Asim Kumar

(Signature)

Balsi